

# **Hyperbaric Chamber Fires: Lessons Learnt**

---

**Dick Clarke, CHT**



# Hyperbaric Chamber Fires

## *Lessons Learnt*

Primary Training in Hyperbaric Medicine  
Columbia, South Carolina

### Factors Precipitating Chamber Fires

- Absence of design/manufacturing codes; code non-compliance
- Lack of a formal fire safety plan
- Inadequate fire safety plan
- Apparently adequate fire safety plan not adhered to
- Unanticipated factors

#### Absence of design/manufacturing codes: code non-compliance



Steel monoplace at 2.4 ATA  
air compressed, mask O<sub>2</sub>; inboard dump  
no analyzer so unknown O<sub>2</sub> concentration

Flash fire  
structural integrity maintained  
hot gases melted door seal, cut through concrete floor, blew out building windows

#### Cause of ignition: non-intrinsically safe communication system



#### Intrinsically safe

- keeping level of electrical energy too low to cause ignition  
*thereby preventing sparks & keeping temperatures low*
- device designs that exclude oxygen  
*plus, purging device with inert gas*
- device strong enough to contain explosion
- moving device outside hazardous (chamber) area

#### No chamber design/construction codes & standards in Peru *some such countries adopt authoritative standards*

#### Lack of adequate operational safety procedures

- no overboard O<sub>2</sub> dump*
- unknown chamber O<sub>2</sub> concentration*
- no pt. grounding*
- oil lubricated air compressor ? filtration*

**Monoplace Chamber Fire  
Lima, Peru, 2006  
Incident Report**

Glenn J. Butler,  
President & CEO

R.W. "Bill" Hamilton, Ph.D  
Hamilton Research

Michael W. Allen,  
Senior Vice President – Operations & Safety

© 2006 Sunder Life Support Technologies, Inc.  
Sunder Life Support Technologies, Inc. is a member  
of the Life Support Technologies Group.  
Life Support Technologies Group  
200 West 10th Street, Suite 1000  
Seattle, WA 98101

**Lack of a formal fire safety plan**



Lauderdale-by-the-Sea, Florida, May 2009  
 fire engulfed chamber & 2 occupants at 1.75 ATA O<sub>2</sub>  
 ~ 4 yo CP pt., 62 yo grandmother  
 ~ his tx started 7 months earlier!  
 operator (trainee) didn't know procedure for  
 emergent decompression  
 ~ tried several times to open door while pressurized  
 both occupants succumbed

Vickers "clam shell" manufactured in 1967  
 Burn pattern again suggested internal speaker as source  
 Legal proceedings:  
 Adult "reached to adjust cushion, static discharge from her clothing jumped to earphone jack"  
 Adult "banged on chamber for five minutes to attract attention"  
 "Nobody was monitoring them and when fire started victims were required to scream and bang on glass (sic) dome to get the attention of a bystander who in turn notified staff of the fire, which caused a delay in decompressing the chamber and freeing the victims before the flash fire occurred. When police deputies arrived, the victims were still in the chamber and on fire"



Numerous pages of safety violations  
 Most damning, set up fictitious inspection company  
 "Certified Hyperbarics" for federal facility certification application  
 Medical Director & CHT "exhibited gross lack of competency, gross inattention, criminal indifference to pt. safety"  
 Both guilty of "aggravated manslaughter of a child & manslaughter by reckless disregard of human life & safety of persons exposed to dangerous effects"

**Lack of a formal fire safety plan**



Steel oxygen-filled monoplace chamber  
 single pt. fatality  
 attempted to smoke cigarette




Hospital admitted responsibility...

"We did not warn pt. that smoking or taking a lighter into the chamber could be dangerous"

**Inadequate fire safety plan**



Multiplace chamber Milan, Italy  
 personal clothes; synthetics/pockets  
 no pt. or IA checks...pockets  
 hood exhaust system disconnected  
 "improperly modified hood latex neck seals allowed O<sub>2</sub> to escape into pt. clothes making patients flammable cylinders"  
 chamber O<sub>2</sub> concentration commonly exceeded permissible limit  
 "O<sub>2</sub> monitor alarm manipulated"



**10 patients and nurse die within seconds in hospital fire**

Several newspaper accounts/Letter to Lancet

Fire lasted ~ 30 seconds

*led some to believe it was extinguished vs burning itself out*

Fire dept official, "fire unstoppable in high O2 content"

*inconsistent with previous water deluge experience*

**Initial official report**

"Patients going into the chamber were checked by two doctors for flammable objects, but something must have slipped through"

**Court proceedings**

"A lady enters the hyperbaric chamber where she is to undergo treatment and brings with her an alcohol-based hand warmer, those with flame. From that hand warmer starts the fire that kills, after a slow agony, all the people who were inside."

**Initial official report**

"Automatic in-chamber fire-fighting system went into immediate action, and the fire was put out within less than one minute"

**Court proceedings**

"The fire extinguishing system was not functioning as the tank that was supposed to contain the water was empty, the propellant compressed air cylinder had the tap closed and the water supply hose valve was closed. The hand shower inside the hyperbaric chamber, foreseen in the design phase, had not been installed."

**Inadequate fire safety plan**

Chamber operator opened 3-way valve to select BIBS O2 source selected >2,000 psig (non-reduced) option reported hearing 'sizzling bacon' sound

Fire immediately erupted from chamber control panel

flame shot out 3 feet/1 meter, spraying molten stainless steel penetrated steel filing cabinet igniting contents chamber tech burned on face, arms, back, as the moved pt. fire extinguished only when O2 supply secured

Facility sprinkler system & fire alarm activated

**News Briefs**

**Oxygen Fire at Shands Teaching Hospital in Gainesville, FL**

**Hyperbaric Medicine Center Dedicated to Dr. Jefferson C. Davis**

**2nd International Meeting on High Pressure Biology**

**Chamber Fire Analyzed**

**Misc. Courses**

**Desautels DA, et al. PRESSURE Nov/Dec 1990**

"Likely cause...high-velocity particle impacts"

ignited valve's Teflon seating & seal material

several fittings significant for "sand blasting" appearance


likely source of particles...HP O2 cylinder valves & piping

Auto-ignition temperature of valve seating 400-700 F/200-370 C

particle friction heating in HP O2 exceeds 1,600 F / 870 C

**Lessons learned-safety standard failures**

- protect disconnected oxygen piping
- oxygen piping "cleaned for oxygen service"
- HP oxygen reduced at source
- quarter turn valves contraindicated > 125 psig
- filtration at source/prior to reducing regulator
- larger diameter piping reduces oxygen velocity/related heating



**Apparently adequate fire safety plan not adhered to**



Istanbul University Medical Center  
 Multiplace chamber fire July 1998  
 3 fatalities: 2 divers, 1 physician

Latter stages extended USN TT 6

Chamber O<sub>2</sub> atmosphere not monitored nor routinely flushed  
*one diver/pt. using mask with overboard exhaust, second using hood with inboard exhaust*

Two "lightsaber-like" oxygen flames seen emitting (via viewport)  
*spontaneous ignition within regulators*

Chamber operator did not/could not activate water deluge  
*Internal fire extinguisher not activated  
 Flames only died out when oxygen system completely exhausted*

Relief valves lifted (10 ATA)

Chamber internal temperature estimated to have exceeded 1,000C/1,800F

Inadequate system maintenance; particularly O<sub>2</sub> delivery system cleanliness

Operational practices inconsistent with recognized standard of care

Physician entered chamber with cigarette lighter

*"In all incidents I have encountered in my 30-year hyperbaric practice, the people who accidentally put a lighter or mobile phone inside are inside attendants and doctors, because patients are checked before each entrance"*

Inadequate/non-existent emergency drills

No visible evidence of burns on deceased (hair/eyelashes intact)





**Apparently adequate fire safety plan not adhered to**

Steel oxygen-filled multiplace chamber

animal pt. fatality

chamber operator fatality

Patient treatment #5 underway

horse unsettled; kicking out

dislodged protective padding overlying steel hull

'massive spark' & flames per CCTV

urgent decompression initiated

**Assistant ran to alert fire service; heard two explosions**

*first smaller, followed in ~1 second by massive one, as chamber exploded*

*sound reported to have been heard several miles away*

*piece of chamber went through apartment window > 2 miles away*

Operator (29 yo) died immediately; blunt force trauma/thermal injuries

remains found buried under chamber debris

Assistant/trainee suffered multi-trauma, including severe head injuries

evacuated to regional trauma center; survived

Horse remained shod (steel)

Not sedated

His coat contained oil-based lotion

not washed with approved soap per FSP

No formal hyperbaric safety training

Authoritative codes re animal chamber construction  
guided but not certified per human standards?

Formal training in hyperbaric technology/safety

Water deluge system?

Methane gas detector-chamber flushing issue?  
becomes explosive 5-17% range in air...? HBO  
loudest explosions >10% in air...? HBO



Year	Type Chamber	Fire/Explosion	Cause	Fire fighting	Severity of the injuries (if full body injury)
1967	Monoplace (O <sub>2</sub> compressed)	Fire	lantern, charcoal pocket warmer	Unknown	1 patient died
1989	Monoplace (O <sub>2</sub> compressed)	Fire	lantern, Petri dish, candle, wet suit	Fire extinguisher	1 patient died
1992	Monoplace (O <sub>2</sub> compressed)	Fire	lantern, Petri dish, candle, wet suit	Fire extinguisher	1 patient died
1996	Monoplace (O <sub>2</sub> compressed)	Fire and Explosion	lantern, lit cigarette, pocket warmer	None	3 dead (1 patient / 2 others)

**Apparently adequate fire safety plan not adhered to**

Initial statement released by hospital was that all recommended safety procedures were carried out

**THE WORLD AS IT IS**

**CONCLUSION**

**REMARKS**

**REFERENCES**

Oxer H. SPUMS Journal 1996;26(4)



Unanticipated factors



Youn B, et al. J Hyperbaric Med 1989;4(2)

Multiplace chamber at 2.0 ATA  
 2 inside attendants  
 4 patients; 3 adults, 1 4-wk-old  
 SOP microwave warming of blankets  
 some pediatric, all neonates

Cotton blanket warmed for 2.5 mins. high setting

Scorched (ironed shirt) smell upon removal


Examined by unfolding several times  
 nothing untoward/not unduly hot

Compressed in medical lock


Upon receipt into chamber IA noticed 2 brown spots  
 blanket immediately developed open flame

IA attempted to reinsert into lock

Chamber deluge activated...twice




Burned 100% cotton blanket




Carbon deposits below medical lock

Pts switched to air breathing  
 Poor visibility resulted in second deluge  
 All occupants uneventfully decompressed  
 Pts counseled & monitored; 3 inpts.  
 All eventually completed their HBO courses  
 Tested microwave warming 2.5-4.0 mins.  
 Scorching not obvious unless blanked fully opened



Scorched areas between creases at 2.5 mins.



Scorched areas between creases at 4.0 mins.

Lack of a formal fire safety plan

