

Hyperbaric Chamber Fires: Lessons Learnt

Dick Clarke, CHT

Hyperbaric Chamber Fires

Lessons Learnt

Primary Training in Hyperbaric Medicine
Columbia, South Carolina

Hyperbaric Chamber Fires

Lessons Learnt

Primary Training in Hyperbaric Medicine
Columbia, South Carolina

Factors Precipitating Chamber Fires

- Absence of design/manufacturing codes; code non-compliance
- Lack of a formal fire safety plan
- Inadequate fire safety plan
- Apparently adequate fire safety plan not adhered to
- Unanticipated factors

Absence of design/manufacturing codes: code non-compliance



Steel monoplace at 2.4 ATA

air compressed, mask O₂; inboard dump
no analyzer so unknown O₂ concentration

Flash fire

structural integrity maintained

hot gases melted door seal, cut through
concrete floor, blew out building windows

Cause of ignition: non-intrinsically safe communication system



Intrinsically safe

keeping level of electrical energy too low to cause ignition
thereby preventing sparks & keeping temperatures low

device designs that exclude oxygen
plus, purging device with inert gas

device strong enough to contain explosion

moving device outside hazardous (chamber) area

No chamber design/construction codes & standards in Peru
some such countries adopt authoritative standards

Lack of adequate operational safety procedures

- no overboard O2 dump*
- unknown chamber O2 concentration*
- no pt. grounding*
- oil lubricated air compressor ? filtration*

**Monoplace Chamber Fire
 Lima, Peru, 2006**

Incident Report

Glenn J. Butler,
 President & CEO

R.W. "Bill" Hamilton, Ph.D
 Hamilton Research

Michael W. Allen
 Senior Vice President - Operations & Safety

Life Support Technologies group

Absence of design/manufacturing codes: code non-compliance

Absence of design/manufacturing codes: code non-compliance

Lack of a formal fire safety plan

Lauderdale-by-the-Sea, Florida. May 2009

fire engulfed chamber & 2 occupants at 1.75 ATA O2
 ~ 4 yo CP pt., 62 yo grandmother
 ~ his tx started 7 months earlier!

operator (trainee) didn't know procedure for emergent decompression
 ~ tried several times to open door while pressurized

both occupants succumbed

Vickers "clam shell" manufactured in 1967

Burn pattern again suggested internal speaker as source

Legal proceedings:

Adult "reached to adjust cushion, static discharge from her clothing jumped to earphone jack"

Adult "banged on chamber for five minutes to attract attention"

"Nobody was monitoring them and when fire started victims were required to scream and bang on glass (sic) dome to get the attention of a bystander who in turn notified staff of the fire, which caused a delay in decompressing the chamber and freeing the victims before the flash fire occurred. When police deputies arrived, the victims were still in the chamber and on fire"


Numerous pages of safety violations

Most damning, set up fictitious inspection company
 "Certified Hyperbarics" for federal facility certification application


Medical Director & CHT "exhibited gross lack of competency, gross inattention, criminal indifference to pt. safety"

Both guilty of "aggravated manslaughter of a child & manslaughter by reckless disregard of human life & safety of persons exposed to dangerous effects"

Lack of a formal fire safety plan




Steel oxygen-filled monoplace chamber
single pt. fatality
attempted to smoke cigarette




Hospital admitted responsibility...

"We did not warn pt. that smoking or taking a lighter into the chamber could be dangerous"

Inadequate fire safety plan



Multiplace chamber Milan, Italy
personal clothes; synthetics/pockets
no pt. or IA checks...pockets
hood exhaust system disconnected
"improperly modified hood latex seals allowed O2 to escape into pt. clothes making patients flammable cylinders"
chamber O2 concentration commonly exceeded permissible limit
"O2 monitor alarm manipulated"



Fire occurred during compression
"red flame explodes on screen, video goes black"
Water deluge system activated...no water emitted
10 pts 1 nurse quickly succumbed

10 patients and nurse die within seconds in hospital fire

Several newspaper accounts/Letter to Lancet

Fire lasted ~ 30 seconds

led some to believe it was extinguished vs burning itself out

Fire dept official: "fire unstoppable in high O2 content"

inconsistent with previous water deluge experience

10 patients and nurse die within seconds in hospital fire
By Peter Dinklage
10 patients and nurse die within seconds in hospital fire
10 patients and nurse die within seconds in hospital fire

Initial official report

"Patients going into the chamber were checked by two doctors for flammable objects, but something must have slipped through"

Court proceedings


"A lady enters the hyperbaric chamber where she is to undergo treatment and brings with her an alcohol-based hand warmer, those with flame. From that hand warmer starts the fire that kills, after a slow agony, all the people who were inside."

Initial official report

"Automatic in-chamber fire-fighting system went into immediate action and the fire was put out within less than one minute"

Court proceedings

"The fire extinguishing system was not functioning as the tank that was supposed to contain the water was empty, the propellant compressed air cylinder had the tap closed and the water supply hose valve was closed. The hand shower inside the hyperbaric chamber, foreseen in the design phase, had not been installed."



Inadequate fire safety plan



Chamber operator opened 3-way valve to select BIBS O₂ source
 selected >2,000 psig (non-reduced) option
 reported hearing 'sizzling bacon' sound
 Fire immediately erupted from chamber control panel
 flame shot out 3 feet/1 meter, spraying molten stainless steel
 penetrated steel filing cabinet igniting contents
 chamber tech burned on face, arms, back, as she moved pt.
 fire extinguished only when O₂ supply secured
 Facility sprinkler system & fire alarm activated

News Briefs

Oxygen Fire at Shands Teaching Hospital in Gainesville, FL

*By David A. Desautels, MPA, MSIT
 Director of Safety, SHS, Inc.
 Steve J. Barber*

The Gainesville Medical Center at the University of Florida Health Shands Teaching Hospital in Gainesville, Florida, experienced a major fire on August 20, 2019. The fire started in a hyperbaric chamber and spread to the control panel, igniting the chamber's oxygen supply. The fire was extinguished by the facility's fire department. The fire caused significant damage to the chamber and surrounding equipment. The fire also resulted in the death of a patient and the injury of several staff members.

Hyperbaric Medicine Center Dedicated to Dr. Jefferson C. Davis

The Gainesville Medical Center at the University of Florida Health Shands Teaching Hospital in Gainesville, Florida, has dedicated a hyperbaric chamber to Dr. Jefferson C. Davis. Dr. Davis was a pioneer in the field of hyperbaric medicine and was instrumental in the development of the hyperbaric chamber at the hospital. The chamber is dedicated to his memory and will continue to provide life-saving treatment to patients.

2nd International Meeting on High Pressure Biology

The second international meeting on high pressure biology was held in Gainesville, Florida, in August 2019. The meeting was organized by the Gainesville Medical Center and the University of Florida. The meeting brought together scientists from around the world to discuss the latest research in high pressure biology. The meeting was a success and resulted in the publication of several papers.

Chamber Fire Analyzed

*By David A. Desautels, MPA, MSIT
 Director of Safety, SHS, Inc.
 Steve J. Barber*

The Gainesville Medical Center at the University of Florida Health Shands Teaching Hospital in Gainesville, Florida, experienced a major fire on August 20, 2019. The fire started in a hyperbaric chamber and spread to the control panel, igniting the chamber's oxygen supply. The fire was extinguished by the facility's fire department. The fire caused significant damage to the chamber and surrounding equipment. The fire also resulted in the death of a patient and the injury of several staff members.

Misc. Courses

The Gainesville Medical Center at the University of Florida Health Shands Teaching Hospital in Gainesville, Florida, offers a variety of courses for its staff members. The courses are designed to help staff members improve their skills and knowledge. The courses include topics such as safety, emergency preparedness, and patient care. The courses are taught by experienced instructors and are highly interactive.

Desautels DA, et al. PRESSURE Nov/Dec 1990

Desautels DA, et al. PRESSURE Jan/Feb 1991

"Likely cause...high-velocity particle impacts"


ignited valve's Teflon seating & seal material
 several fittings significant for "sand blasting" appearance
 likely source of particles...HP O₂ cylinder valves & piping

Auto-ignition temperature of valve seating 400-700 F/200-370 C

particle friction heating in HP O₂ exceeds 1,600 F / 870 C

Lessons learned-safety standard failures

- protect disconnected oxygen piping
- oxygen piping "cleaned for oxygen service"
- HP oxygen reduced at source
- quarter turn valves contraindicated
- filtration at source/prior to reducing regulator
- larger diameter piping reduces oxygen velocity/related heating



Apparently adequate fire safety plan not adhered to



Istanbul University Medical Center
 Multiphase chamber fire July 1998
 3 fatalities: 2 divers, 1 physician

- Latter stages extended USN TT 6
- Chamber O₂ atmosphere not monitored nor routinely flushed
 one diver/pt. using mask with overboard exhaust, second using hood with inboard exhaust
- Two "lightsaber-like" oxygen flames seen emitting (via viewport)
 spontaneous ignition within regulators
- Chamber operator did not/could not activate water deluge
 Internal fire extinguisher not activated
 Flames only died out when oxygen system exhausted
- Relief valves lifted (10 ATA)

Inadequate system maintenance; particularly O2 delivery system cleanliness

Operational practices inconsistent with recognized standard of care

Physician entered chamber with cigarette lighter

"In all incidents I have encountered in my 30-year hyperbaric practice, the people who accidentally put a lighter or mobile phone inside are inside attendants and doctors, because patients are checked before each entrance"

Inadequate/non-existent emergency drills



Apparently adequate fire safety plan not adhered to

Steel oxygen-filled multiplace chamber

animal pt. fatality

chamber operator fatality

 A photograph showing a horse inside a hyperbaric chamber. A person in a blue uniform is standing next to the chamber, operating the controls. The chamber is a large, white, cylindrical structure with a dark door.

Patient treatment #5 underway

horse unsettled; kicking out

dislodged protective padding overlying steel hull

'massive spark' & flames per CCTV

urgent decompression initiated

 A photograph showing a person in a black shirt operating a hyperbaric chamber. The chamber is a large, white, cylindrical structure with a dark door. The person is standing next to the chamber, looking at a control panel.

1504668
MARION COUNTY
SHERIFF'S OFFICE

REPORT NO: 010101
MARION COUNTY
SHERIFF'S OFFICE

REPORTED BY: 414 MARION JONES REPORTED ON: 07/01/2025

ON 07/01/2025, I RESPONDED TO THE INCIDENT LOCATION AND ARRIVED AT APPROXIMATELY 10:05 AM. ON ARRIVAL, I MADE CONTACT WITH INCIDENT COMMANDER TERRY BUCKLEWORTH, ENGINE 23 OF THIS RESERVE AND HE ADVISED ME OF THE INCIDENT AND FIRST HAND INFORMATION.

I THEN MADE CONTACT WITH THE MANAGER OF THE FACILITY, REPORTER LINDORA BRYNE, WHO CONTINUED WITH HIS INFORMATION. SHE ADVISED THE POSITION OF ONE OF THE OPERATOR WAS STATIONARY AND SHE STAYED AT THE FACILITY AND SHE POINTED HIM OUT TO ME AS HE WAS STANDING NEAR THE HORSE. SHE ALSO ADVISED ME WITH A NAME OF LARRY BRYNE, WHO WAS STANDING IN THE CORNER AND SHE SAID HE WAS THE NAME OF CHARLOTTE, CLERMONT AND HER PHONE NUMBER, HOWEVER, SHE WAS NOT ABLE TO PROVIDE A CONTACT NUMBER TO MAKE CONTACT WITH BRYNE. SHE SAID SHE HAD A NUMBER BUT SHE COULD NOT RECALL IT.

I THEN CONTACTED LEUTENANT GLOBERG, WHO WAS ON SCENE, THE DISTRICT COMMANDER, AND HE ADVISED ME THAT HE HAD A NUMBER TO CONTACT LINDORA BRYNE AND I ASKED HIM TO PROVIDE ME WITH AN ADDRESS IN AN EFFORT TO LOCATE HER TO BE SUBJECT TO THE ACCIDENT, TO REMOVE THROUGH THE AREA THAT HAD BEEN IDENTIFIED.

I INITIATED A CRASH SCENE LOG AT 10:08 HOURS. I THEN TOOK ALL PERSONS INFORMATION MADE TO ME AND ASKED THOSE WHO WERE THERE FOR THEIR OWN OFFICIAL CAPACITY TO THE OFFICE OF THE SHERIFF. I ALSO ADVISED DETECTIVE BRYNE THAT SHE COULD CONTACT THE SHERIFF'S OFFICE TO LOCATE LINDORA BRYNE AND DETECTIVE PHILIPPA STIGALL, I WAS ADVISED DETECTIVE STIGALL WAS THE LEAD DETECTIVE ON THE SCENE AND AT THE TIME, I TOOK THE POSITION OF ASSISTING THE SCENE LOGS AND THE LOGS WERE DONE.

DURING THAT TIME, AGENTS FROM THE STATE FIRE MARSHAL'S DEPARTMENT ARRIVED ON SCENE, ALONG WITH THE FIRE DEPARTMENT COMMANDERS.

CROSS PROVISIONAL SPECIALIST JESSIE TURNER WAS ALSO ARRIVED ON SCENE TO ASSIST WITH THE LOGS AND THE MEDICAL EXAMINER'S OFFICE ARRIVED ON SCENE TO CONDUCT HIS INVESTIGATION.

A REPRESENTATIVE WITH OSHA ARRIVED ON SCENE TO CONDUCT HIS INVESTIGATION. OSHA STAFF WITH AGENCY, OSHA AND OSHA STAFF, AND ANIMAL WELFARE OFFICER FROM MARION COUNTY ARRIVED ON SCENE. THE OSHA STAFF AND ANIMAL WELFARE OFFICER STAYED AT THE SCENE DURING THE INVESTIGATION AND ANIMAL WELFARE OFFICER STAYED WITH THE HORSE. THE OSHA STAFF AND ANIMAL WELFARE OFFICER STAYED AT THE SCENE DURING THE INVESTIGATION AND ANIMAL WELFARE OFFICER STAYED WITH THE HORSE. THE OSHA STAFF AND ANIMAL WELFARE OFFICER STAYED AT THE SCENE DURING THE INVESTIGATION AND ANIMAL WELFARE OFFICER STAYED WITH THE HORSE.


AT THE CONCLUSION OF THE INVESTIGATION, THE DEPT OF THE INCIDENT

Assistant ran to alert fire service; heard two explosions

first smaller, followed in ~1 second by massive one, as chamber exploded

sound reported to have been heard several miles away

piece of chamber went through apartment window > 2 miles away



Operator (29 yo) died immediately, blunt force trauma/thermal injuries remains found buried under chamber debris

Assistant/trainee suffered multi-trauma, including severe head injuries evacuated to regional trauma center; survived



Horse remained shod (steel)

Not sedated

His coat contained oil-based lotion not washed with approved soap per FSP


No formal hyperbaric safety training

Authoritative codes re animal chamber construction guided but not certified per human standards?




Formal training in hyperbaric technology/safety


Water deluge system?

Methane gas detector-chamber flushing issue? becomes explosive 5-17% range in air...? HBO loudest explosions >10% in air...? HBO



Year	Type Chamber	Fire/Explosion	Cause	Fire fighting	Severity of the injuries (if full body burn)
1967	Monophase (O ₂ compressed)	Fire	Ignition, closed pocket w/air	Unknown	1 patient died
1989	Monophase (O ₂ compressed)	Fire	Ignition, Plasma cath/ox w/air	Fire extinguisher	1 patient died
1992	Monophase (O ₂ compressed)	Fire	Ignition, Plasma cath/ox w/air	Fire extinguisher	1 patient died
1996	Monophase (O ₂ compressed)	Fire and Explosion	Ignition, Disposable pocket w/air	None	3 dead (1 patient / 2 others)



Apparently adequate fire safety plan not adhered to

THE WORLD AS IT IS


THE WORLD AS IT SHOULD BE

THE WORLD AS IT IS

THE WORLD AS IT SHOULD BE

Oxer H. SPUMS Journal 1996;26(4)

Initial statement released by hospital was that all recommended safety procedures were carried out



NBS Monthly Safety Notice

January 2002 National Biomedical Services, Inc.

Importance of Optimizing Chamber Gas Flow

In this notice, attention is focused on the importance of using fully and consistently optimized gas flow through the chamber.

The standard 2000L mono-place hyperbaric chamber operates under a state of constant gas (oxygen) flow. Flow can be adjusted to control the amount of oxygen that is available to the patient in the "closed" position. The control valve permits approximately 200 L/min. of flow, as designed, and to avoid a potentially hazardous accumulation of CO₂, flow control is completely stopped. In the fully open position, flow speeds of 1000 L/min. are available. The control valve between these two settings provides a corresponding flow volume range between 200 and 400 L/min.

The constant flow of gas serves to eliminate metabolic waste gases and provides a useful source of temperature control for the patient. Higher flow speeds also cool chamber walls, lower flow rates reduce the cooling effect.

However, there are additional aspects to flow control, aspects that have important patient and facility safety implications.

The principal source of oxygen for hyperbaric compression and constant flow is the standard liquid oxygen (LO₂) system. The oxygen is stored in a pressure-cooled and insulated tank. As it is released, an expansion is produced. This expansion is a variable gas, so an associated venting system, having led off from the tank, is required to vent the gas. It is essential that this venting system be properly maintained.

While an air gas for the benefit of minimizing residual damage to system venting and piping. This potential adverse effect on metabolic activity is a direct consequence of greater accumulation of static electricity. A resulting static electrical discharge may generate sufficient energy to cause ignition of volatile substances. Hydrocarbon-based and oil-based alcohol-based products, such as disinfectants, are particularly susceptible.

Key Operational Issues

- Under routine operations, as the rate of gas flow through the chamber is decreased the chamber atmosphere's relative humidity increases. This effect is the result of a greater accumulation of the patient's exhaled moisture within the chamber. This is a good thing.
- In the patient's complete physiological state, low flow of oxygen flow, don't provide additional benefits. This is all too frequently the fact. In fact, if it happens on increasing safety hazard. Should be occur within the chamber, more likely to be a problem. The accumulation of moisture on the walls of the chamber results in the chamber walls. This may result in catastrophic failure of the chamber, and potential damage to the facility and staff.
- If a patient complains of being too warm:
 - Cover them with a sheet rather than a blanket.
 - Close the chamber at a slow rate of descent in order to stop the effect of compression on their circulation.
 - Reduce chamber flow increase rate for patient comfort, not for regulation of the whole unit, and a carbon dioxide level.
 - Administer an antipyretic to the patient.
- If a patient complains of being too cold:
 - Close the exhaust valve.
 - If this isn't sufficient, switch the sheet out for a blanket.
- Get into the habit of observing the oxygen flow settings upon start of the medical treatment procedure. Don't just adjust in a position where treatment is underway, and you do not know precisely the flow settings.

Note: Know the flow rate of all lines. Optimize for patient comfort.

Reading Assignment: *Hyperbaric Facility Safety: A Practical Guide*, ed. by Thomas T. 1999, 2002, 2004.

Inadequate fire safety plan

One of several chambers Naval Hospital Central Jakarta, Indonesia

Fire & "explosion" > 4 deaths

3 pts. 1 physician

room filled with smoke > several occupants hospitalized (2 remained so at 7 days)

